

American Standard

PRESSURE BALANCE TEMPERATURE/VOLUME CONTROL VALVE

MODEL NUMBER

R121SS

COLONY SOFT
TRIM


MODEL NUMBER

T675.500

TUB SPOUT

MODEL NUMBER

8888.056



Appropriate finish code


CHROME

002

2-WAY DIVERTER VALVE

MODEL NUMBER

R422



HERITAGE HANDLE DIVERTER TRIM

MODEL NUMBER

T342.430

HOT LINE FOR HELP

For toll-free information and answers to your questions, call:

1 (800) 442-1902

Mon. - Fri. 8:00 a.m. to 8:00 p.m. EST

Saturday 10:00 a.m. to 4:00 p.m. EST

IN CANADA 1-800-387-0369

(TORONTO 1-905-306-1093)


Weekdays 8:00 a.m. to 7:00 p.m. EST

IN MEXICO 01-800-839-1200



M965667 Rev. 1.0 (1/17)

American Standard



3-FUNCTION HAND SHOWER

1660766.002
(1.5 gpm)

1660767.002
(2.5 gpm)

WALL SUPPLY

8888.037.002


8888037.002
WALL SUPPLY




M962520-0020A
CHECK VALVE



030782-0020A
HOSE KIT



M9641800020A
SPRAY HOLDER
ASSEMBLY





METAL HOSE


8888.035.002

36" SLIDE BAR

1660.236.002



M964179-0070A
MOUNTING KIT



Appropriate finish code

CHROME **002**

HOT LINE FOR HELP

For toll-free information and answers to your questions, call:
1 (800) 442-1902

Mon. - Fri. 8:00 a.m. to 8:00 p.m. EST

Saturday 10:00 a.m. to 4:00 p.m. EST

IN CANADA 1-800-387-0369

(TORONTO 1-905-306-1093)

Weekdays 8:00 a.m. to 7:00 p.m. EST

IN MEXICO 01-800-839-1200



PART OF LIXIL

M965667 Rev. 1.0 (1/17)